January 14, 1980



931706

Mr. Robert Lemma Hobert Brothers Company 600 West Main Street Troy, Ohio 45373

Dear Mr. Lanmo,

On January 10, 1980 your waste disposal area located off of Lytle Road was inspected by Mr. Domigan and myself from this department.

The inspection revealed that the two large holes at the site were still present. The hole near the NON-RESPONSIVE constitutes a potential hazard to the water supply of that residence should any dumping of waste material occur.

The second hole is presently being filled in with a gray flux material that has been classified as solid waste by the Ohio Environmental Protection Agency. All solid waste must be disposed of at a licensed solid waste disposal site only. A solid waste disposal site shall not be operated unless a license is issued by the local board of health pursuant to Section 3734.05 of the Ohio Revised Code.

Other solid waste in the form of trash and garbage was present in the area where you are storing the large metal barrels.

The above-mentioned conditions constitute a violation of Section 3734.02, 3734.05, and 3734.11 of the Ohio Revised Code and Regulation No. 71-2.1 of the Mizmi County and Troy City Health District.

You are therefore requested to fill in the above-mentioned two large excavations on the Hobart Brothers property with dirt, soil, stones, or other non-toxic substance that is not classified as solid waste within fifteen (15) days of your receipt of this letter.

I would suggest that you contact either Don Marshall or Joe Moore at the Southwest District office of the Ohio E.P.A. concerning possible nearby licensed solid waste disposal sites which you might utilize to dispose of the powdery material.

Sincerely,

Donald R. Tucker
Public Health Sanitarian

DRT/jm

certified mail-return receipt #2243847

cc: Prosecuting Atty.
Don Marshall, Ohio E.P.A.

SANITARY LANDFILL INSPECTION FORM

LICENSED

MIAMI COUNTY HEALTH DISTRICT

.: 9	HEALTH DISTRICT			
Mame of Landfill HOBART BROTHERS	WEST BROCK AREA	Location	TRADE SO WEST	
Name of Operator BOB LAMME	·	Address	RIOGÉ	
Method of Operation - Trench	Area		Other	·-··
Estimated Daily Receipts - Loads	Tons		Cubic Yards	
irea of Landfill - Total Acres				
General Characteristics of Site - Quarry			Hillside	
			Other	
iours of Operations				
Geographic Area Served		Population Ser	ved	
,icense Number	Salvaging Permitted - Yes		No	
I tems marked by (X) are in violation.				
I. SITE - HE-24-04	IV. OPE	ERATION - HE-	24-09	
Ground Water Protection	(a) Operated According to	Plan	(i) Vector Control	
Surface Runoff	(b) Access to Site Limited		General Operation	
- · · · · · · · · · · · · · · · · · · ·	(c) Dumping Area Restricte		Supplemental Control	
	(c) Blowing Paper & Debris		(j) Salvaging	
	(d) Equipment Adequate (d) Equipment Repair		(k) Animals Excluded	
Odor Control	(e) Properly Spread		(1) Fire Protection (m) Hot or Burning Loads	
Smoke donated	(e) Properly Compacted		(n) Records	
II. DUMPING & BURNING - HE-24-06	(f) Covered Material Adequa	ate	(0) Responsible Party	
Open Dumping	(f) Covered Daily		Present _	
Open Burning	(f) Finished Cover Adequat			
	(g) Finished Grade Adequat			
II APPROVALS	(h) Special Material Handl Sewage Solids	ing		
Site - HE-24-07	Sewage Liquids			
Plan - HE-24-08	Hazardous Subst	ances	_	
COMMENTS AND RECOMMENDATIONS:				
	WERE STILL THERE	- 44.4	IT ADD - AMED TURT	
170 100 1110	We he sill 1146x		IT APPEARED THAT	·
NG MORE LIQUID	WASTE HAD BEE	N PUT	INTO THEM	
MATERIAL CA GA	CAY FLUX) CONSIN	EREO A	Y THE CHIO E.P.A	
	VASTE WAS BEIN			
SEVERAL PILES	OF THIS MATERIA	L PRES	ENT. DOMESTIC	
TRASH WAS	1650 PRESENT.			
1 DISCUSSED THE	SITUATION WITH DO	ON MAR	SHALL OF THE	
Cilia E On				
CHIO E-PA.				
			7 /	
TAN 10 1980		Venalel	Sanitarian	
. =				

H - 4825, 10